

## Mazda MX-5 NC

### Ignition Coil Connector Repair Kit

functionality:

- Solves the issue commonly found in pre-facelift Mazda MX-5 NC models (2006–2008): rough idling, misfires, jerking, power loss, and ECU error codes P0300 ... P0304.

Installation Requirements:

- Soldering skills.

